

Appendix A

19 Spring Street

PID 25031626











Unoccupied Unit

Interior walls separating from exterior walls.



Interior Walls separating from exterior walls.



Main floor bathroom. Interior walls separating from exterior walls.



Significant water damage to main floor kitchen.



Significant water damage to main floor kitchen.



Oven was on, element appeared to be burnt out.



Floor has completely collapsed into basement. Hallway door frame is resting on debris.



Refrigerator has fallen into the basement due to the collapsed floor.



Main floor water damage.



Main floor water damage.



Main floor water damage.



Main floor water damage.



Space heater on and running.




Main floor water damage, hoarding.



Main floor hoarding.




Main floor hoarding.



Second-floor water damage.



Second-floor hoarding/garbage.



Second-floor hoarding/garbage.



Second-floor hoarding/garbage.



Second-floor water damage.



Second-floor water damage.



Second-floor bathroom water damage.



Second-floor bathroom water damage.



Second-floor bedroom. Light fallen onto mattress and papers.



Second-floor bedroom. Light appeared to scorched wallpaper.



Occupied Unit

Water damage on second-floor.



Minor water damage on second-floor.



Electrical and furnace is accessible through occupied unit.



Basement: Main gear box in extremely poor condition. Accessible through occupied unit



Basement. Collapse of unoccupied unit.

