

19 Spring Street

PID 25031626









Interior wall has
separated from
exterior wall






**Kitchen has collapsed into basement
and little to no floor remains (refrigerator
has fallen into the basement)**





**Interior wall separates
unoccupied kitchen
and occupied kitchen.**













**Second floor of
unoccupied unit
(over the main floor
dining/living space
of the occupied)**



**Second floor of
unoccupied unit
(over the main floor
dining/living space
of the occupied)**





**Main gear switch and
fuse box in basement
of the occupied unit**



**Kitchen has collapsed into
basement. Many electrical wire
and water lines run through the
debris.**



**Water lines
and electrical**



**Basement
stairwell of
unoccupied unit**



