

# SYNOPSIS

## 196 East Victoria Street

---

Various complaints have been received regarding the physical condition of the building located at 196 East Victoria Street. Town staff, as well as a contract Building Official from the Municipality of the County of Cumberland have investigated and determined that this structure poses an immediate and real threat to not only the inhabitants of the structure but also to the general public.

The owner was ordered by the Administrator to provide an engineering assessment of the building on the property, however to date this has not been received and the owner has made no attempt to correspond with the Town on this matter.

Given the historical lack of compliance from the owner of this property, the current state of the buildings, and the likely costs of renovation to bring the buildings into compliance with the Town's Minimum Standards for Residential Occupancies Bylaw, the Administrator is recommending that the buildings be demolished.

### **MOTION:**

**That the Planning Advisory Committee order the buildings at 196 East Victoria Street be demolished, and back fill the hole within 30 days from the date of this Committee meeting, with all work to be done by the property owner. Failure by the property owner to do the work will result in the Town completing the work and send all contents of the building to the Cumberland Joint Services Management Authority land fill with all costs charged to the property owner's tax account.**